

Release Notes

Model: HS-1600T MARK II

Apr.18, 2024

HS-1600T MARK II Firmware

- Version: MBv1.78.1.08/SP V2.6
- File Name: HS1600T MARK II_USB_MBv1.78.1.08_KBv4.0
 - HS1600T.bin
 - HS1600TM.bin
 - HS1600TMP.bin

Issues

1. Users can operate the OSD menu even when the AT is turned on.
2. Fixed the issue of the OSD Menu indicator for entering the second layer of the OSD Menu and then exit the OSD Menu. When the OSD is turned on, the indicator will be lit in red, and when exiting the OSD Menu totally, the indicator will be lit in white.

Mar.29, 2021

HS-1600T MARK II Firmware

- Version: MBv1.78.1.08/SP V2.6
- File Name: HS1600T MARK II_USB_MBv1.78.1.08_KBv3.6
 - HS-1600TMP.bin: MB firmware v1.78+SP v2.6 for GB913N0
 - HS-1600T.bin: KB firmware v3.6 for GB-913 KB.

Issues

1. Fixed the issue that when the resolution is switched for the Multiview out (1080i to 1080p), it may cause a no-screen issue.

Sept., 24, 2020

HS-1600T MARK II Firmware

- Version: MBv1.75.1.08_KBv3.6
- File Name: HS1600T_USB_MBv1.75.1.08_KBv3.6
 - HS-1600TMP.bin: MB firmware v1.75+SP v2.6 for GB913N0
 - HS-1600TM.bin: MB firmware v1.75 for GB796N0-A
 - HS-1600T.bin: KB firmware v3.6 for GB-913 KB.

Issues

1. Fixed the issue that there are some noises that will appear in some colors when the Multiview OUT is set at 1080p25 and 1080p30.

Aug., 18, 2020

HS-1600T MARK II Firmware

- Version: KB V. 3.6
- File Name: HS-1600T MARK II FW V1.71.1.08SP V2.6 for GB913N0
 - HS-1600TMP.bin: MB firmware v1.71+SP v2.6 for GB913N0
 - HS-1600TM.bin: MB firmware v1.71 for GB796N0-A
 - HS-1600T.bin: KB firmware v3.6 for GB-913 KB.

Issues

1. Fixed the signal lost issue when connecting with the PTC-140T.
2. Improved the One Push WB function. When the One Push WB is executed, the HS-1600T's LED will be blinking in red and the camera control will be prohibited until the time (5 seconds for PTC-140T and 2 seconds for the PTC-150T) is finished, and then the LED indicator signal will be resumed and the camera control function will also be resumed.
3. Fixed the issue that the resolution of the PTC-140T will change from 1080i 59.94 to 1080i60.

Aug., 12, 2020

- Version: FW V1.71.1.08/SP V2.6 for GB913N0
- File Name: HS-1600T MARK II FW V1.71.1.08SP V2.6 for GB913N0
 - HS-1600TMP.bin: MB firmware v1.71+SP v2.6 for GB913N0 (CH1 loop out is added)
 - HS-1600TM.bin: MB firmware v1.71 for GB796N0-A
 - HS-1600T.bin: KB firmware v3.1 for GB-913 KB.

Issues

1. When the output source is in DVI format to the HDMI Input 1, it will cause the color cast issue.

Jun., 23, 2020

HS-1600T MARK II Firmware

- Version: MB v1.71.1.08+SP V2.2
- File Name: HS-1600T MARK II MB v1.71.1.08+SP V2.2
 - HS-1600TMP.bin: MB firmware v1.71+SP v2.2 for GB913N0 (CH1 loop out is added)
 - HS-1600TM.bin: MB firmware v1.71 for GB796N0-A

-
- HS-1600T.bin: KB firmware v3.3 for GB-913 KB.

Issues

1. Fixed the issue that when the MB connection is finished, and the status packet is obtained, the scanning is not finished, so, the status update LED indicator will be bypassed.
2. The center point for zooming is widened for solving the issue of continuous zooming and the out of control of the camera due to that the difference of the VR is over the center point range.

Jun., 9, 2020

HS-1600T MARK II Firmware

- Version: MB v1.71.1.08+SP V2.2
- File Name: HS-1600T MARK II MB v1.71.1.08+SP V2.2
 - HS-1600TMP.bin: MB firmware v1.71+SP v2.2 for GB913N0 (CH1 loop out is added)
 - HS-1600TM.bin: MB firmware v1.71 for GB796N0-A
 - HS-1600T.bin: KB firmware v3.1 for GB-913 KB.
- Merged_BL_V2.0_HS-1600T_V3.1.hex

Issues

1. Initial release for the HS-1600T MARK II firmware.
 2. GB796-KB-A burns the merged_BL_V2.0_HS-1600T_V3.1.hex will become the GB-913-KB.
-