

Release Notes

Model: HS-2850

Date: Mar. 2, 2020

Firmware

FlashUpdate_v3.88

Issues

1. Menu added item: 31 Tally Mode (NORMAL & AUDIO CONTROL MODE)

Date: Mar. 13, 2019

Firmware

FlashUpdate_V3.79

Issues

1. Fixed the issue that the Still Picture can not be uploaded.

Date: Feb. 27, 2019

Firmware

FlashUpdate_V3.79

Issues

1. Added HDMI OUTPUTS MODE (RGB/YUV422/YUV444) : item 16 within the OSD.

Date: Jul. 23, 2018

Firmware

FlashUpdate_V3.74

Datavideo_SwitcherUtilities_V2.5_build 10.11.2017

Issues

1. Added XPT function.
-

Date: May 17, 2018

Firmware

FlashUpdate_V3.68

Datavideo_SwitcherUtilities_V2.5_build 10.11.2017

Issues

1. Fixed the T-bar transition issue.

PS: Due to that there are different key board versions including old and new (e.g., GB764-KB or GB764-KB-A), when the software is updated to V3.68, the "change mode of operation" is displayed. Please select the second option (Force writing latest firmware version), and then press Next step to continue updating the software.

Date: May 11, 2018

Firmware

FlashUpdate_V3.67

Datavideo_SwitcherUtilities_V2.5_build 10.11.2017

Issues

1. Fixed the jitter issue on ch2 and ch6 in MV 8ch.

Date: Mar 29, 2018

Firmware

FlashUpdate_V3.66

Datavideo_SwitcherUtilities_V2.5_build 10.11.2017

Issues

1. Added output formats 1080P25/29/30
2. Fixed SDI output instability

Date: Aug 21, 2017

Firmware

FlashUpdate_V3.45

Datavideo_SwitcherUtilities_V2.5_build 22.07.2017

Issues

1. Fixed the disrupted LED indications on the control panel when GPI = ON and T-BAR MODE = TWO WAY.
 2. Fixed the disrupted OSD Menu numbering.
 3. In the 12-Channel configuration, a Multiview mode of 2 big screens (PGM and PVW) added on top of 8 small screens at the bottom is added.
-

Date: Jul 14, 2017

Firmware

FlashUpdate_V3.42

Datavideo_SwitcherUtilities_V2.5_build 10.04.2017

Issues

Improvement: Audio/Video Sync error status can be monitored on WFM-8300 for 14hr.

Date: Jul 7, 2017

Firmware

FlashUpdate_V3.39

Datavideo_SwitcherUtilities_V2.5_build 10.04.2017

Issues

1. Audio is turned off unexpectedly (analog in/SDI out and HDMI out, or 1k tone out)
 2. Removed all CVBS related items in the OSD MENU
-

Date: Apr 11, 2017

Firmware

FlashUpdate_V3.33

Datavideo_SwitcherUtilities_V2.5_build 10.04.2017

Issues

1. When the input source is HD-SDI with 1080P50(25)/59(29)/60(30), the SDI OUT image is moved downwards by approximately three lines (Compared to SDI in).
 2. In 1080i/59 mode, CH8 HDMI IN becomes unstable.
 3. 1080i59 mode/ch1-ch12: set all of audio delay to 2, noise is heard on CH4 HDMI input.
 4. Tested with 8 ports, but the MV Mode B and Mode D do not display 8 INPUT screens.
 5. Sometimes the MV Out is found flashing after changing to 1080i/50 mode from 1080i/59. Relevant items cannot be configured in the MENU and reboot is required.
 6. HDMI Multiview: In Mode C and Mode E, the audio indicator is displayed incorrectly.
-

Date: Feb 21, 2017

Firmware

FlashUpdate_V3.26

Datavideo_SwitcherUtilities_V2.5_build 09.02.2017

Issues

1. Fixed the audio delay noise.
 2. Fixed HDMI instability problem
 3. Fixed RS-422 connection problem
-

Date: Feb 9, 2017

Firmware

FlashUpdate_V3.23

Datavideo_SwitcherUtilities_V2.5_build 06.02.2017

Issues

1. Fixed the unexpected AUTO button behavior.
 2. Fixed the instability issue in the HD-SDI input 1 picture.
-

Date: Jan 24, 2017

Firmware

FlashUpdate_V3.16

Datavideo_SwitcherUtilities_V2.5_build 06.01.2017

Issues

1. Fixed the countdown image overlap issue.
 2. Fixed the multi-screen noise (CH 4/8/12 windows) in the 1080i/59.94 mode.
-

Date: Jan 05, 2017

Firmware

FlashUpdate_V3.15

Datavideo_SwitcherUtilities_V2.5_build 16.07.2016

Date: Aug 01, 2016

Firmware

FlashUpdate_V2.70

Datavideo_SwitcherUtilities_V2.5_build 13.06.2016

First build
