Release Notes

Model: PTC-205

May.14, 2026

PTC-205 Firmware

- **Version: FW: SOC V2.2.3 2026-4-27/ARM V1.1.3 2026-4-23 /AF V1.1.2 2026-4-3**
  - **File name: D-PTC205_NDI_SY20X_V2.2.3_R_20260427.mrg/PTC205_ARM_V1.1.3_20260423.mrg**

Issues

1. Fixed the abnormal tilting speed issue when the camera is controlled by the controller keyboard.
2. Modified the VISCA command to control the Iris of the camera.
3. Changed the camera name to PTC205 when queried via the VISCA command “ENQ:network”.
4. Optimized the DVIP command processing logic to solve the issue where sending the DVIP command “81 01 06 06 02 FF” via UDP/5002 caused the camera to reboot.
5. Fixed the issue where clicking “Default” on the “Stream” page of the Web UI failed to restore settings to factory defaults.