Release Notes

Model: SE-2600/HS-2600 Firmware Release Info

Oct. 07, 2024

Firmware Versions

- S/W v1.3.2.3
- K/B v1.1.4

File name: se3200_se2600_USB_v1.3.2.3_kb_v175_114_boot_install

Issues

For S/W v1.3.2.3

1. The HS-2600 is supported, the HS-2600 model name can be displayed by the OSD and DVIP finder.
2. After the K version mainboard is supported, the SW6 will be used for switching between models.

For SE-2600/HS-2600 KB v1.1.4

1. Added the T-bar calibration procedure to prevent the issue that transition can not be done after pulling down the T-bar.
   a. SE-2600/HS-2600: While the power-on LED is scanning, press "PGM BLK" + "PVW BLK" at the same time. You will see the LED in the upper right corner of the T-bar. When the "CUT" LED is blinking, it means that the T-bar adjustment procedure is beginning.
   b. Push the T-bar all the way up, press the "CUT" button, the T-bar pulling up position will be memorized and the LED on the bottom right of the T-bar, which is the "AUTO" LED, will flash.
   c. Push the T-bar all the way down, press the AUTO button, and the T-bar pulling down position will be memorized and the "FTB" LED will flash.
   d. Press the FTB button again to exit the calibration program and enter the normal program. Afterwards, the T-bar will switch scenes according to the memorized points during operation or the next time it is turned on.
   e. After entering the T-bar calibration procedure, if you want to give up the memorized points, you can press the "CLIP" button directly to delete the pre-saved memorized points and to exit the T-bar calibration procedure. After the pre-saved memorized points are deleted, the T-bar transition will be done by detecting the position by the Variable Resistor.
2. Allowed a small margin for the transition error.

Aug. 30, 2024

Firmware Versions

- S/W v1.3.2.1b
- K/B v1.1.3

File name: se3200_se2600_USB_v1.3.2.1b_kb_v175_113_boot_install

Issues

1. Fix the issue where pushing the T-BAR to either side may not switch scenes.
2. Fix the OSD Simplified Chinese translation (S/W version still shows vl.3.2.1).

May. 23, 2024

Firmware Versions

- S/W v1.3.2.1
- K/B v1.1.0

File name: se3200_se2600_USB_v1.3.2.1_kb_v175_110_boot_install

Issues

1. Enable the AA-filter function of SE-2600 to improve the MV/PIP picture quality and make the mitered sawtooth not visible.

2. Improved the issue of slow response of KB operation when MENU is opened.

3. Improve the problem that KB may crash when switching resolution or CKAuto.

4. Added MENU and FTB LED indicators for the keyboard, when those two buttons are pressed, they will be lit.