

Release Notes

Model: PTR-15/PTR-15T

May.5, 2026

Firmware

Version: V1.0

File Name: PTR-15_PTR-15T v.1.0 FW Update 20260508

Issues

- 1 Fixed an issue where Group Play could not select Preset numbers higher than 99.
 2. Fixed a one-digit offset issue for VISCA Commands in Group Play. e.g. (G1->G2)
 3. Added a deviation correction option of +1 to DVIP preset numbers.
 4. Added a VISCA Command to stop Group Play by pressing ENTER.
-

Aug.12, 2025

Firmware

Version: V0.92

File Name: PTR-15_PTR-15T v.0.92 FW Update 20250812

Issues

- 1 Improved RS422 or DVIP control response for showcase100.
 2. Fixed the issue where the first DVIP command is ineffective.
 3. Resolved the problem where pan/tilt VISCA commands do not respond after enabling Free-D.
 4. Improved the issue where updating software sometimes needs to be done twice.
-

Jan.14, 2025

Firmware

Version: V0.76

File Name: PTR-15_PTR-15T v.0.76 FW Update 20250122

Issues

- 1.Improved the stability of the free-D interface.
 - 2.Added the output delay time setting to improve the free-D position synchronization.
 - 3.Added the 19.5V selection for the camera output power.
 - 4.Decreased the switch speed of the camera output power voltage.
-

Oct.24, 2024

Firmware

Version: V2.0.1.3

File Name: DVIP Firmware Update v.2.0.1.3 for PTR-15

Issues

1. Shortens the time it takes to accept a reconnection after an abnormal network disconnection.

Note: This DVIP firmware update is for PTR-15 only.

Jul.08, 2024

Firmware

Version: V0.73

File Name: PTR-15_PTR-15T v.0.73 FW Update 20240819

Issues

1. Fixed the issue that the RMC-180MK2 can not keep the correct speed LED signals when switching to speed-Middle.
 2. Fixed the V0.71 PTR-15T issue that there is no HDMI output for the HDBaseT after powering on.
-