
Release Notes

Model: DAC-70

Jul. 1, 2022

Firmware

Version: 2.1.0.3

File name: DAC-70 FW 2.1.0.3 Firmware Update

1. The software v2.1.0.3 is released for GB577N0-D.
 2. The detection time is extended for solving the issue that the LED green light may be off when connecting to an SDI signal.
-

Nov. 6, 2019

Firmware

Version: V 0.1.4.0

File name: DAC70-FW-0140.BIN

1. Added the 2SI payload format.
 2. Fixed the issue of the 8bit payload.
 3. Added the 3G SDI Level B format.
-

Jan 25, 2018

Firmware

Version: V 0.1.3.8

File name: DAC70-FW-0138

1. Fixed the audio indicator display error in VGA input mode and HDMI output mode.
-

Dec 15, 2017

Firmware

Version: V 0.1.3.7

File name: DAC70-FW-0137.BIN

1. Fixed the audio indicator display error in VGA mode.
-

Sept 19, 2017

Firmware

Version: V 0.1.3.6

File name: DAC70-FW-0136.BIN

1. Added the 720x508 format.
 2. Corrected the MURIDEO PATTERN GEN issue (FADING MODE)
-

Mar 29, 2017

Firmware

Version: V 0.1.3.4

File name: DAC70-FW-0134.BIN

Issues

1. Fixed the OSD display error after the video source is switched to VGA (60.00 -> 60.59).

2. Fixed the issue of no SDI audio when the video source is SD-SDI upon boot.
-

Jan 5, 2017

Firmware

Version: V 0.1.3.3

File name: DAC70-FW-0133.BIN

Issues

1. Fixed the HDMI color range issue (FULL/LIMITED RANGE).
-

Aug 5, 2016

Firmware

Version: V 0.1.3.1

File name: DAC70-FW-0131.BIN

Issues

1. Fixed DAC-70 device boot issues.
 2. Added PSF format.
-

Nov 9, 2015

Firmware

Version: V 0.1.2.8

File name: DAC70-FW-0128.BIN

Issues

1. Will return to normal in about five seconds; fixed the LED display confusion due to static electricity.
-