

## Release Notes

---

### Model: PTC-140

---

Jun.14, 2024

Firmware

**Version: PTC-140 CAMERA 2.7.5/MCU 3.2.5/AF4.0.9**

**File Name: D-PTC-140\_ARM\_V3.2.5\_20240516.mrg/ D-PTC-140\_SY20X\_V2.7.5\_R\_20240515\_AF\_V4.0.9\_R\_20200905.mrg**

#### Issues

##### CAM:

1. Modify DVIP to release completely after disconnecting.
2. Optimize Processing Logic.
3. After upgrading to the new version 3.2.5 MCU, reset the presets and you can use it at normal speed. Or just restore the default parameters.
4. Added UDP broadcast reply under dvip.

##### MCU:

1. Modifying the Return Value of the Enquiry Shutter Command.
2. Modified the issue that it is invalid for querying the Gain Command.
3. Synchronized the latest VISCA command List (Shutter/Gain/IRIS).

---

Jul.21, 2022

Firmware

**Version: PTC-140 CAMERA 2.7.0/MCU 3.2.2/AF4.0.9**

**File Name: D-PTC-140\_ARM\_V3.2.2\_20220422.mrg/ D-PTC-140\_SY20X\_V2.7.0\_R\_20220520\_AF\_V4.0.9\_R\_20200905**

#### Issues

1. Added the Tally Light option into the OSD menu (The default setting is RED/GREEN, if this option is set to "OFF", the tally light of the camera will not be lit.)
2. Improved the Firefox and Safari web browsers (please clean the cache for the web browser).
3. Deleted GB28181, local configuration, and RTSP authentication within the Web UI.
4. Fixed the issue that the SRT stream can not be streamed to Bilibili website.
5. Fixed the issue that users can not log into the web UI when entering the "User Name" and "Password" after opening the web UI for a long time.

---

May.04, 2022

Firmware

**Version: PTC-140 CAMERA 2.6.7/MCU 3.2.0/AF4.0.9**

**File Name: D-PTC-140\_ARM\_V3.2.0\_20210323.mrg/ D-PTC-140\_SY20X\_V2.6.7\_R\_20201130\_AF\_V4.0.9\_R\_20200905.mrg**

## Issues

1. Added 8x 09 7E 7E 04-05 FF VISCA over IP inquiry (WD, R Gain, B Gain and etc. )
2. Added reboot function when you change the network settings on the PTC-140 series OSD.
3. Added Tally light On/Off commands: (TALLY ON: 8x 01 7E 01 0A 00 02 FF, TALLY OFF: 8x 01 7E 01 0A 00 03 FF)

Feb.08, 2022

Firmware

**Version: PTC-140 CAMERA 2.6.8/MCU 3.2.1/AF4.0.9**

**File Name: D-PTC-140\_ARM\_V3.2.1\_20210727.mrg/ D-PTC-140\_SY20X\_V2.6.8\_R\_20210720\_AF\_V4.0.9\_R\_20200905.mrg**

## Issues

1. Added the Tally light menu in the OSD (The default value is RED/GREEN, if this option is turned off, the tally light will not light up).

ired ON	81 01 7E 01 0A 00 02 00 FF	ired OFF	81 01 7E 01 0A 00 03 00 FF
igreen ON	81 01 7E 01 0A 00 00 02 FF	igreen OFF	81 01 7E 01 0A 00 00 03 FF
Tally ON	81 01 7E 01 0A 00 02 FF	ired OFF	81 01 7E 01 0A 00 03 FF

2. Improved the Firefox and Safari web browsers (Please clear the web browser cache for verification).
3. Removed the GB28181, local configure, and RTSP Authentication in the web UI.

Jan.25, 2021

Firmware

**Version: PTC-140 CAMERA 2.6.7/MCU 2.5.8/AF4.0.9**

**File Name: D-PTC-140\_ARM\_V2.5.8\_20201211.mrg/ D-PTC-140\_SY20X\_V2.6.7\_R\_20201130\_AF\_V4.0.9\_R\_20200905.mrg**

## Issues

1. Fixed the issue that when modifying the IP address and DHCP settings, those settings can not be saved in the OSD menu.
2. The "8x 09 06 12 FF" command which is issued by the VISCA over IP is addressed according to the rule of returned message for regular models rather than Datavideo customized returned message rule.

Nov.25, 2020

Firmware

**Version: PTC-140 CAMERA 2.6.6/MCU 2.5.7/AF4.0.9**

**File Name: D-PTC-140\_ARM\_V2.5.7\_20201014.mrg/ D-PTC-140\_SY20X\_V2.6.6\_R\_20201023\_AF\_V4.0.9\_R\_20200905.mrg**

### Issues

1. The SRT function is added.
2. Added the DHCP ON/OFF reminder and IP address displaying for the OSD menu.
3. The web player plugin is changed to HTML5.
4. The default audio input is changed to LINE IN and the volume level is 2.

---

Oct.22, 2020

Firmware

**Version: PTC-140 CAMERA 2.6.2/MCU 2.5.6/AF4.0.6**

**File Name: D-PTC-140\_ARM\_V2.5.6\_20200915/ D-PTC-140\_SY20X\_V2.6.2\_R\_20200317\_AF\_V4.0.6\_R\_20190821**

### Issues

1. Fixed the issue that when the SET Preset/Call Preset operations are done when assigning the color temperature, the color temperature setting will be abnormal.

---

Mar.31, 2020

Firmware

**Version: PTC-140 CAMERA 2.6.2\_2020.3.17/MCU 2.5.5\_2019.12.16/AF4.0.6\_2019.8.21**

**File Name: D-PTC-140\_ARM\_V2.5.5\_20191216.mrg  
D-PTC-140\_SY20X\_V2.6.2\_R\_20200317\_AF\_V4.0.6\_R\_20190821.mrg**

### Issues

1. The VISCA over IP is added.
2. Audio Input selection option (Mic in /Line in switching) is added for the web control UI.
3. The RTMPS protocol is supported.

---

Dec.18, 2019

Firmware

**Version: PTC-140 CAMERA 2.5.7/MCU 2.5.4/AF4.0.6**

**File Name: D-PTC-140\_ARM\_V2.5.4\_20191115.mrg**

### Issues

1. The 10x digital zoom is added.

---

Oct. 15, 2019

Firmware

**Version: PTC-140 CAMERA 2019.8.20/MCU 2.5.3\_2019.9.5/AF4.0.6\_2019.8.21**

**File Name: D-PTC-140\_ARM\_V2.5.3\_20190905.mrg  
D-PTC-140\_SY20X\_V2.5.7\_R\_20190820\_AF\_V4.0.6\_R\_20190821.mrg**

### Issues

1. The AF version is 4.0.6 for fixing the reversing issue of the Focus NEAR/Focus Far when

- using the Manual Focus function based on 4.0.3.
2. Modify the issue that it is invalid for setting the Host Name.
  3. The default audio is AAC, 128K (The Stereo is deleted).
  4. Modify the issue that when the shutter speed is changed from 1/120 to 1/180, the brightness of the screen will become insufficient. The issue "when the Gain value is changed from 4 to 3, the screen will become brighter" is also fixed.
  5. Modify some traditional Chinese translations for some web UI options
  6. Modify the issue that when the DHCP mode is turned on, if users use the remote controller to resume the system back to the factory default situation, the factory default IP will not be 192.168.5.163.
  7. Fix the issue that when the system is resumed to the factory default situation, the system language will not be changed.
  8. Fix the issue that when the output video format is set as i50, the main stream in the Video Encode option can be set as 50 frame Rate and the sub stream can be set as 30 frame rate. (The correct setting must be max. 25 frame rate for both main stream and sub stream).
  9. The Enable checkbox on the web UI can control the turn-on or turn off of the HDMI.
  10. Fix the issue that the Tally light of the PTC-140 will be lit simultaneously. There is one kind of Tally signal can be lit at one time.
  11. Modify the jitter issue of i50/60/59.94.
  12. The AF is 4.0.4. According to customers' request, in manual Focus mode, the Focus will not follow.
  13. The issue that the Zoom IN setting can not be saved after powering off the camera is fixed.

---

Mar. 29, 2019

Firmware

**Version: Camera 2.5.2 2019-3-15/MCU 2.4.6 2019-3-14/AF 4.0.3 2019-2-21**

**File Name: D-PTC-140\_SDI\_ARM\_V2.4.6\_20190314.mrg**

**D-PTC-140\_SY20X\_V2.5.2\_R\_20190315.mrg**

### Issues

1. Initial release for Camera FW 2.5.2 2019-3-15, MCU FW 2.4.6 2019-3-14 and AF firmware 4.0.3 2019-2-21.
  2. The AF firmware is packaged together with the CAMERA firmware, please check the latest firmware No. of the AF by the OSD the camera or by the Web UI.
  3. There are three firmware numbers including MCU, CAMERA and AF, the firmware release date must be checked together when confirming the firmware version.
-