

## Release Notes

---

### Model: HS-1650T Firmware Release Info

---

**Feb. 13, 2026**

Firmware Versions

- KBD Software v1.1.15

File name: HS-1650T FW v1.1.15 Firmware Update

#### Issues

1. When pulling the T-bar to the middle and then stop, the PGM and PVW signals will not be exchanged after pressing "CUT" and "AUTO" buttons.
  2. Fixed an issue where the Multiviewer (MV) would display two red frames when stopping the T-bar halfway, setting PIP and Luma Key to PVW, pressing the CAM button for an Image Key, pressing CUT, and then pulling the T-bar to the end.
  3. The AT status will be wrong when the HS-1650T is connected to the PTC-305T camera and the movement time is long.
  4. Pressing an Image Key for a disconnected PTC camera will now display a 'Disable' message.
-